

Effect of conservation treatments on heritage stone. Characterisation of decay processes in a case study.

M.J. Varas-Muriel ^{a,b,*}, E.M. Pérez-Monserrat ^a, C. Vázquez-Calvo ^a, R. Fort ^a

^a Instituto de Geociencias IGEO (CSIC, UCM), C/José Antonio Novais 12, 28040, Madrid, Spain.

^b Facultad Ciencias Geológicas, Universidad Complutense de Madrid (UCM), C/José Antonio Novais 12, 28040, Madrid, Spain.

*E-mail address: mjvaras@geo.ucm.es

Tf- +34913944918, Fax- +34915442535

ABSTRACT

Preliminary studies are an imperative when determining the impact of conservation treatments on historical materials. The Romanesque apse on a church at Talamanca de Jarama, Madrid, Spain, whose dolostone was severely decayed by rainwater and salts, was treated in the past with substances that ravaged the restored area. Petrological techniques showed that salts leached out of the cement under the roof onto the stone cornice whose surface had been coated with synthetic resins. During evaporation, the salts precipitated in the stone and underneath the resin, inducing blistering, fissuring, flaking, scaling and detachment of part of the restored decorative elements.

Keywords: dolostone, conservation treatments, cements, synthetic resins, architectural heritage, decay, petrological techniques.

1. INTRODUCTION

Time and weathering (water, wind, solar radiation, temperature variations, air pollution...) are the chief agents of decay in most stone materials comprising the built heritage. The impact of such decay varies depending on the composition and texture of the materials involved [1-3].

The need to conserve the cultural heritage has driven the appearance on the market of many restoration products, designed and manufactured primarily to retard stone decay and increase its durability [4-7]. These products may be: inorganic (such as “lime wash” - $\text{Ca}(\text{OH})_2$ (aq) used in the nineteenth century and presently recovered in the form of nanolime - $\text{Ca}(\text{OH})_2$ alcoholic colloidal nanoparticles [8]) or organic, which may in turn be divided into natural (scantly processed animal or plant substances) or synthetic (primarily highly processed petroleum derivatives) compounds. A third group of products, organosiliceous derivatives such as ethyl silicates or alcoxysilanes, combines organic and inorganic compounds. All three groups are designed to: a) consolidate the internal components of the stone (consolidants); b) waterproof surfaces (water repellents); or c) rendering surfaces or fill in joints, cracks, fissures, or gaps in the stone itself (restoration mortars).

40 Further to international recommendations, the use of such restoration products should be limited and
41 controlled, and only applied if they are clearly beneficial, their long-term efficacy is proven and they
42 entail no risk whatsoever for people or the environment [9-11].

43 Synthetic resin and cement restoration mortars have been used profusely in recent years, for they
44 bond well to the substrate and are highly weatherproof [4-7, 12-15]. Nonetheless, several ICOMOS
45 Charters [9-11]) advise against using such restoration mortars in any form unless a detailed study
46 has been conducted of their long-term performance and durability. The rationale for such
47 recommendations may lie in these compounds' possible failure to meet the aims for which they
48 were initially designed (render, infill, restitution of lost material,...): when combined with other
49 construction materials they may respond in unintended ways, even generating undesirable by-
50 products such as salts. The composition of synthetic restoration mortar varies depending on its
51 intended purpose and the construction materials with which it is to be in contact. As a general rule,
52 such mortars comprise a binder (cement, lime/hydraulic lime or gypsum), siliceous or carbonaceous
53 sand aggregate, pigments for colour and admixtures such as polymeric resins, silicone or siloxane
54 resins, acrylic resins, epoxy resins, fluorinated polymers or unsaturated polyesters [12, 14-15].

55 Like decay itself, conservation and restoration products perform differently depending on the type
56 of stone to which they are applied and on environmental conditions. Hence the need for preliminary
57 studies [6, 12, 16-18], firstly to characterise the composition and texture of the stone substrate. In
58 particular its porosity must be determined (pore percentage, shape, size and distribution) and its
59 condition assessed (forms, causes, processes and agents of decay), paying close heed to local
60 environmental factors or microclimatic conditions inside the building to be conserved [6-7, 12, 19-
61 20]. That should be followed by a field or/and laboratory study of the restoration products and
62 application techniques to establish their efficacy, their compatibility with and suitability for the
63 stone substrate, and their durability in the prevailing climate [1, 7, 12-14, 16-17, 20].

64 While preliminary studies are called for in international recommendations and protocols for action
65 on world cultural heritage conservation (e.g., Athens 1931, Venice 1964, Restauro 1987 Charters, to
66 name a few; ICOMOS), they are often absent in restoration project design and implementation. The
67 distressing result has been that many interventions in heritage buildings have accelerated decay in
68 the materials they set out to protect [1, 12, 14, 17, 21].

69 Moreover, since the full chemical formulation of market products is normally unknown, preliminary
70 trials provide information from which to more or less accurately predict their possible long-term
71 behaviour [7, 16-18, 21-23]. This is of particular relevance because the original chemical
72 composition of these products may vary with time, depending on their interaction with the material
73 to be restored and the local environment, and may become irreversible for disposal. In a similar
74 vein, gaining a subsequent understanding of the product applied and the application technique used
75 may be a complex task if no documentary record of the intervention is available [12, 14, 17].

1.1. San Juan Bautista Church at Talamanca de Jarama, Madrid, Spain: apse construction and restoration

San Juan Bautista Church is located at Talamanca de Jarama, a village 45 km NNE of Madrid, Spain. Characterised by two architectural styles, Romanesque (twelfth-thirteenth centuries) and Renaissance (sixteenth century), the church is made of dolostone, limestone and quartzite ashlar and rubble stones; brick masonry; earthen infills; and mortars, both as jointing and as render. The rectangular presbytery and semi-circular apse (Fig. 1) are all that is left of the original Romanesque dolostone building. The rectangular nave or main body of the church, consisting of three aisles with varying heights, was rebuilt in Renaissance style in the sixteenth century with a wide variety of construction materials (stone, brick and mortars). In 1885, with the church in ruins, the south wall and bell tower were rebuilt. The building was listed as a historic-artistic monument in 1931 and has been protected as such ever since.

The semi-circular apse was built around four pilasters that delimit five walls or infills. Its three windows are located in alternate infills (Fig. 1). The stone masonry consists of rough ashlar at the base and more refined ashlar in the upper areas. The floral, geometric and human forms carved out of the stone modillions and cornice, are of significant historic and artistic value (Figs 2 and 3). The dolostone on the apse, traditionally used in the area, was quarried from nearby Upper Cretaceous geological formations [24].

The two types of dolostone were quarried from different geological strata. One, beige-coloured, compact and scantily porous, is found in the rough ashlar at the base, while the other, a yellowish and more porous stone, is found in the upper walls ashlar, including the decoratively carved modillions and cornice (Figs 1 and 2). The former is known as *Piedra de Torrelaguna* (*Torrelaguna stone*) and the latter and more workable, *Piedra de Redueña* (*Redueña stone*) [2]. Some of the stone in the dado and underneath the modillions was replaced (possibly in the 1885 intervention) with the same varieties of dolostone as the original material. The lighter tone cladding visible in the same areas was laid during the 1990 restoration (Fig. 1).

In the late nineteen seventies, the apse was observed to be largely decayed, due primarily to the damp accumulating in the dado, cornice and windows, attributed respectively to capillary moisture rising from the subsoil, rainwater leakage and surface runoff. The main causes of decay in the cornice were the poor condition of the roof and the lack of any means to evacuate rainwater. The effect of rainfall (475 mm/year) is more conspicuous in the spring and autumn. A design for intervention proposed in 1982, rather vaguely and with no mention of preliminary studies, called for “repairing the roof, chipping away the mortar-patina covering the entire apse and replacing the ashlar and other architectural elements with stone similar in appearance to the original material”.

110 The design specified that the walls were to be cleaned with spray-dried water and scoured with
111 ammonium bi-fluoride, after which protective treatment (Primal AC-234 acrylic resin with methyl
112 methacrylate and ethyl acrylate co-polymers) would be applied. The joints and cracks were also to
113 be cleaned and filled with cement or/and (Araldite BY-154) epoxy resin and (AFA 55/60) siliceous
114 sand. In the most damaged part of the cornice, some of the carved decorative elements had fallen
115 away and many others were severely decayed. Restoration was to consist of the application first of a
116 pure epoxy resin consolidant and then of (Araldite BY-154) epoxy and (Primal AC-33) acrylic
117 resins mortars containing siliceous sand to reconstitute forms and textures.

118 The visual inspection undertaken on the occasion of the present study, in the absence of written
119 records on whether this restoration design was implemented as envisaged or partially or fully
120 modified, revealed that the intervention conducted in 1990 primarily affected the Romanesque apse.
121 One of the measures adopted at the time was to replace a few ashlar with white limestone quarried
122 outside the region that differs from the original stone (Fig. 1). The roof was weatherproofed with a
123 grey portland cement mortar under the arabic roof tiles, that was also laid directly on the cornice
124 (Figs 2 and 3); joints and cracks were filled in with cement and synthetic mortars (Fig. 3); and a
125 number of conservation products were applied in an attempt to protect the decorative elements on
126 the cornice as far as possible (Fig. 3). By 2005, the restored stone exhibited conspicuous and
127 troubling signs of decay: the decorative elements on the cornice were severely deteriorated, with
128 risk of detachment [25].

129

130 The present study aimed to: a) assess the state of decay in the carved stone on the Romanesque
131 cornice prior to the 1990 intervention; b) ascertain the type of restoration products used in that
132 intervention; c) establish the degree of interaction with and the suitability of these products for the
133 stone and other materials; and d) define the mechanisms involved and the type of decay induced by
134 these products. Petrological techniques, regarded as one of the first analytical methods to be
135 deployed prior to restoration, were applied to meet these objectives. The observation, description
136 and direct and objective classification of decay to small-scale in a material constitute a sound basis
137 for defining the agents, causes and processes of damage and for endorsing the findings of other
138 more complex and subjective analytical approaches.

139 2. MATERIALS AND METHODS

140 The samples studied were taken from the yellow dolostone on the upper area of the original apse,
141 and primarily from the elements carved into the modillions and cornice. Three 5 cm diameter,
142 15-cm long core samples were taken from an ashlar underneath the cornice (Fig. 4a), along with
143 fragments of varying size from the cornice itself (Fig. 4b).

144 Petrological, mineralogical and chemical composition were analysed with the techniques described
 145 below to characterize the cornice materials and determine its state of conservation, and theorise
 146 about the causes and mechanisms involved in the poor response of the stone to the treatments
 147 applied.

- 148 - Polarised light optical microscopy (PM) was conducted to Spanish and European standard
 149 UNE-EN 12407 [26] on an Olympus BX51 petrographic microscope fitted with an Olympus
 150 DP12 digital camera. The samples were so severely segregated that they had to be consolidated
 151 with epoxy resin prior to preparing the 3x2-cm, 30- μ m thick thin sections, dyed with alizarin
 152 red [27] to differentiate calcite from dolomite. PM afforded information on the composition,
 153 texture and microstructure of the materials sampled.
- 154 - Electron microscopy (SEM-EDS) studies were performed on a JOEL JSM 6400 scanning
 155 electron microscope fitted with an Oxford-Link Pentafet energy dispersive X-ray microanalyser.
 156 Small fragments ($\sim 1.7\text{ cm}^3$) and thin sections of the samples were scanned under a secondary
 157 electron (SE) beam. Both types of samples were graphite-coated with a BALZERS MED 010
 158 deposition system, to make them conductive. SEM revealed component microstructure and
 159 texture on a smaller and more detailed scale than PM. In addition, the use of EDS in point mode
 160 furnished a semi-quantitative chemical analysis of the components.
- 161 - Crystalline minerals were identified on a PHILIPS PW 1752 X-ray diffractometer fitted with a
 162 copper anode tube and PC-ADP diffraction software. XRD patterns were acquired operating at
 163 40 kV and 30 mA at 2θ angles of $2\text{--}65^\circ$ with a 0.02-step scan, a speed of 2° per minute, $\text{CuK}\alpha$
 164 radiation and a graphite monochromator. The powder fraction (particle size under $50\text{ }\mu\text{m}$) of the
 165 total samples, were analysed.
- 166 - Solid samples were exposed to micro X-ray diffraction (μXRD) to identify certain mineral
 167 phases on a micrometric scale. The facility used was a PHILIPS X'Pert MPD diffractometer
 168 with a double goniometer, $\text{CuK}\alpha$ radiation and a curved Cu monochromator. Measurements
 169 were taken at 45 kV and 40 mA. μXRD patterns were acquired in the $2\text{--}65^\circ$ 2θ range using a
 170 0.02-step scan at a rate of 1° per minute.
- 171 - The chemical composition of the conservation treatments was found with Fourier transform
 172 infrared spectroscopy (FTIR) on a NICOLET Magna FTIR 750 analyser at a resolution of
 173 0.5 cm^{-1} and a working range of $4\,000\text{--}350\text{ cm}^{-1}$. The samples were powdered and pressed into
 174 potassium bromide (KBr) pellets. Qualitative analysis was based on the specifications and
 175 recommendations proposed by Derrick et al. [28].
- 176 - Dolostone petrophysical characterisation and evolution were determined from density, open
 177 porosity, water absorption (UNE-EN 1936 [29]) and ultrasonic P-wave pulse velocity (V_p)

(UNE-EN 14579 [30]) findings. These physical properties were measured at normal atmospheric pressure and ambient temperature. The tests were conducted on both the outer and inner areas of the cores. The Vp values were found on a PUNDIT CNS ELECTRONICS LTS portable analyser, fitted with 54 kHz, 50-mm diameter transducers.

3. RESULTS

3.1. Cornice: state of conservation

The yellow dolostone on the cornice was found to be severely decayed and many of its decorative elements to have been totally or partially lost after the 1990 restoration (Fig. 3). Some of the conservation treatments contributed to the decay of the dolomite substrate (Fig. 5). The main forms of decay detected were: a) surface gloss and change in hue from yellow to grey in the carved stone due to the presence of a viscous film (Figs 4b and 5); b) blistering, fissuring, flaking and scaling both in the surface treatment and the carved stone, resulting on occasion in detachment (Fig. 5); c) saline sub-efflorescence and crypto-efflorescence beneath the treatments, affecting the carved stone; and d) surface wear (Figs 2, 3 and 5).

3.2. Characterisation and condition of the stone substrate

The dolostone on the cornice is a carbonate rock, uniform in appearance whose ~20-% porosity consisted of pores of < 500 µm in diameter (visual estimate; Fig. 4a). The sub-parallel cracks up to 1.5 cm deep on the surface exposed to the elements induced scaling and detachment with the concomitant loss of the figures carved in the stone (Figs 5 and 6).

The PM study revealed that this massive dolostone is characterised by rhomboid micritic dolomite crystals measuring <10 µm on average and 20-25-% intercrystalline porosity (Figs 7a and 7b).

Some of these subrounded (mean diameter = 225 µm) or irregularly shaped (mean diameter = 975 µm) pores were filled with ≥30-µm sparry calcite crystals. Disperse monocrystalline quartz grains (±5 %) with a mean size of <150 µm (very fine sand) were observed inside the dolomicritic mass (Fig. 7a). The numerous dark iron gel spots also observed were partially responsible for the yellow-golden tone of this variety of stone (Fig. 7a), classifiable as a dolomudstone [31]. The mineralogy detected under the PM (dolomite and some quartz) was confirmed by the XRD findings.

The intense cracking on the sample surfaces increased in the outward direction (Fig. 7b). These cracks, parallel and sub-parallel to one another and to the outer surface of the sample, were 75 µm thick on average and over 250 µm thick in the outer-most areas.

Further to the petrophysical findings (Table 1) this is a dense (>2 800-kg m⁻³) but highly open porosity (24-26 %) stone, properties that were observed to vary from the outer-most decayed

211 (0-5 cm) to the inner (5-10 cm) intact inner area of the cores. The porosity in the outer stone was up
212 to 8 % higher than in the inner stone, which translated into 10 % greater water sorptivity. Such
213 higher surface porosity was confirmed by the nearly $1\,000\text{-m}\cdot\text{s}^{-1}$ lower ultrasonic P-wave velocity
214 (V_p) in that area than in the inner stone.

215 3.3. Characterisation of conservation treatments

216 This study detected the presence of three types of conservation treatments.

217 A- The cornice has a 1 to 8-mm thick grey mortar rendering containing white particles that adapts
218 to the surface irregularities in the intensely cracked stone substrate (Fig. 6). This mortar bonded
219 apparently well to the stone, although not uniformly, for the non-filled millimetric pores found in
220 some areas may have facilitated detachment (Figs 6 and 8).

221 From the petrological (PM) standpoint, this mortar was observed to be a dark, granular, uniform and
222 massive mix of crypto-crystalline (crystal size $<4\,\mu\text{m}$), sub-angular limestone aggregate of varying
223 size (0.125-0.250 and 0.5-1 mm) agglutinated in a partially carbonated, light colour matrix-binder
224 with a microcrystalline texture (crystal size $<10\,\mu\text{m}$) (area A in Fig. 8a). The aggregate-binder
225 interface was well-defined with no chemical reactions taking place around the edges. Porosity was
226 $<5\%$ and characterised by circular to semi-circular pores with a mean diameter of 0.5 mm. The
227 μXRD mineralogical analysis confirmed that the aggregate was calcite and the binder calcite with
228 some quartz (Fig. 8b).

229 Under SEM (area A in Fig. 8c, and Fig. 9), the mortar exhibited dark, dense, viscous areas (matrix-
230 binder) sharply interfaced with lighter micro-granulated areas (aggregate). EDS revealed that the
231 chemical composition of the two areas differed clearly. Despite the graphite coating on the samples,
232 the dark binder area (point A in Fig. 9) exhibited a much higher C (organic component)
233 concentration than the lighter aggregate area (point B in Fig. 9), which in contrast had more Ca
234 (calcite) than the binder. Other chemical elements present in the two areas, although more
235 prominently in the binder, included Si, Mg, Al, Na and Cl (neither Cl nor Na were found in the
236 aggregate). A detailed study of the binder revealed the presence of small (3-5- μm) Ca (calcite)
237 particles inside a C-high dark, dense gel with some Si.

238 The FTIR spectrum for this mortar (Fig. 10) contained a vibration band in the $1\,740\text{-cm}^{-1}$ region
239 associated with carbonyl ($\text{C}=\text{O}$) and an especially intense vibration band at around $1\,440\text{-cm}^{-1}$
240 attributed to carbonate groups ($-\text{CO}_3^-$). The bands detected at around 714, 730, 876, $1\,440$, $1\,800$
241 and $2\,530\text{-cm}^{-1}$ were attributed to calcite (CO_3Ca). The intense vibration band in the $3\,430$ to
242 $3\,540\text{-cm}^{-1}$ region as well as the absorption band at around $1\,620\text{-cm}^{-1}$ were associated with
243 hydroxyl (structural O-H) and amine (N-H) groups. The bands at $1\,440$ and $2\,890$ to $3\,030\text{-cm}^{-1}$

were attributed to the C-H group and the ones at 1020-1250 cm⁻¹ with C-N and C-O groups. The weak vibration band at 1 080 cm⁻¹ was associated with the presence of silicic acid (Si-O-Si).

B - This restoration mortar and at times the stone itself were found to bear a 25 to 50-µm thick coating (area A in Fig. 11a). A viscous film adapted to the surface irregularities of the substrate, it explained the surface gloss observed (Fig. 4b and area A in Fig. 11b). According to EDS analysis, its chemical composition included Ca, C (less than in the mortar) and some Si (point A in Fig. 11b).

The FTIR spectrum for the coating (Fig. 12) differed clearly from the pattern for the restoration mortar. The very intense vibration band in the 1 740 cm⁻¹ region associated with a carbonyl group (C=O) predominated over the band at 1 450 cm⁻¹ attributed to carbonates (-CO₃⁼). The bands detected in the 714-, 876-, 1450- and 2 530-cm⁻¹ regions were generated by calcite (CO₃Ca). The intense vibration band at around 3 430 to 3 540 cm⁻¹ as well the band at 1 630 cm⁻¹ were associated with hydroxyl (structural O-H) groups. The intense bands at 1 450 and 2 880 to 2 970 cm⁻¹ were attributed to the C-H group and the ones at 750 to 800, 1 070, 1 160, and 1 250 to 1 270 cm⁻¹ to C-O groups. Silicic acid (Si-O-Si group) appeared in the form of weak bands in the 471-, 523-, 675- and 1 070-cm⁻¹ regions. C-O and C-H groups were also prominent in this film.

C - In the cracked stone substrate (areas C in Fig. 8 and D in Fig. 13), the Ca-, Mg- and Fe-bearing dolomite crystals and the inter-crystalline and fracture porosity were covered with a thin film only detectable under SEM. Its main (EDS-analysed) chemical composition included Si and Al, while C was scanty present. PM observation (Figs 7 and 8) revealed the presence of this treatment indirectly, for the fracture porosity was not filled with the salts detected.

3.4. Characterisation of saline degradation products

According to the petrographic (PM, XRD and SEM-EDS) findings, appears a new mineralogical component, micro-crystalline gypsum - SO₄Ca·2H₂O (areas B in Fig. 8 and C in Fig. 13). It was detected below the conservation surface treatments, primarily at the interface between the restoration mortar and the cracked dolostone, where it formed a massive irregular layer 0.5 to 1 mm thick (Figs 8 and 14a). It also appeared inside the cracked stone where it formed subspherical growth nodules (Figs 8 and 14) up to 300 µm in diameter, interconnected by thin capillaries (Fig. 14b). The gypsum nodules were observed at depths of up to 1.5 cm and to migrate outward to the stone surface where they formed the layer of variable thickness under the restoration mortar (Fig. 14a). No gypsum fill was found in the cracks in the stone substrate.

4. DISCUSSION

The main type of decay found in the *Piedra de Redueña* [2] dolostone forming the carved cornice on the Romanesque apse was intense inner cracking parallel to the surface, at depths of up to 1.5 cm (Figs 6 and 8). On the surface, this cracking translated into flaking and scaling liable to detachment.

278 The main agents of decay identified were rainwater and soluble salts due to continuous leaking and
279 surface runoff, by the poor pre-1990 condition of the roof and the total absence of gargoyles and
280 gutters to evacuate rainwater. Cracking, characteristic of this variety of stone when exposed to
281 water and salts [32], was the type of decay exhibited by the dolostone in the cornice prior to the
282 1990 restoration [25].

283 This stone's high open porosity (~25 %, Table 1) makes it a readily workable and easy to carve but
284 at the same time scantily durable material [2, 32]. For that reason, it was used on the upper areas of
285 the apse, including the cornice, while a similar but less porous and hence more durable variety
286 (*Piedra de Torrelaguna*, [2]) was laid in the lower areas.

287 The mortar covering the carved dolostone in the cornice, applied in 1990 to reconstitute the lost stone
288 (Figs 6, 8, 9 and 13), appeared to be a mix of lime powder with at least two types (epoxy and
289 acrylic) of synthetic resins and mudstone-like limestone aggregate [31] (Figs 8 and 9). The
290 restoration design drafted in 1982 specified neither the lime (actually calcite - CO_3Ca) binder nor
291 the limestone aggregate (Fig. 9). The synthetic resins in this mortar were identified on the grounds
292 of the vitreous and viscous appearance of the binder under SEM-SE (Figs 9 and 13) [17-18], the
293 EDS-detected presence of high levels of carbon (C) (Figs 9, 11 and 13) and the carbonyl group
294 ($\text{C}=\text{O}$) revealed by FTIR analysis (Fig. 10) [4, 27]. Inasmuch as the resins were mixed, their
295 chemical composition would be very difficult to ascertain with absolute certainty. One of the resins
296 may be regarded as acrylic given the FTIR identification of C-O and C-H groups, while the
297 presence of N-H and C-N groups in the other denotes an epoxide composition [4, 27]. The existence
298 of the epoxy was also confirmed by the EDS detection of NaCl (point A in Fig. 9), which may have
299 arisen during hardening [4]. Both types of resins were called for in the 1982 design. The quartz
300 (μXRD – Fig. 8b), Si and Al (EDS - point A in Fig. 9) and Si-O-Si groups (FTIR – Fig.10) found in
301 this restoration mortar, in turn, suggested the possible presence of a third, silica compound-based
302 consolidant [12, 17-18] or a possible chemical change in one of the synthetic resins used. No
303 written information was available to corroborate the presence of such a third conservation product.

304 The viscous, glossy film covering both the aforementioned restoration mortar and at times the
305 dolostone itself contained both Ca and C (Figs 11 and 13). The identification of $\text{C}=\text{O}$, C-O and C-H
306 groups was an indication that it may have been an acrylic resin [5, 28] mixed with lime powder
307 (Fig. 12).

308 In another vein, the treatment applied prior to the restitution mortar in 1990 was designed to
309 consolidate the decayed dolostone by sealing its cracks (Figs 8 and 13). The EDS identification of
310 silicon (Si) and aluminium (Al) with very little carbon (C) may have been the result of the presence
311 of a silica compound-based product [12, 17-18] similar to the substance detected in the mortar,

rather than the epoxy resin specified in the 1982 design. This product appeared (PM-SEM) to have penetrated to a suitable depth (1.5-2 cm), filling most of the cracks in the stone. Proof of such effective penetration was that the gypsum that appeared as an undesirable by-product of decay did not precipitate into these cracks (Figs 8 and 14a). Good penetration is an essential feature of consolidants used in restoration [6-7, 12, 16, 33].

The gypsum ($\text{SO}_4\text{Ca}\cdot 2\text{H}_2\text{O}$) present in this area was generated after the 1990 restoration and appeared to be the direct cause of the accelerated decay observed in the restored cornice. It adopted the form of sub-efflorescence underneath the treatments used to restore the cornice ornaments and crypto-efflorescence inside the cracked stone (Figs 8, 13 and 14). While internal, this mineral was not attributable to the dolostone, for the salts originated during stone decay, such as epsomite or hexahydrite, are magnesium sulfate-based [34]. Rather, its origin was associated with the grey portland cement mortar laid in 1990 both underneath the apse roof tiles and directly on the carved cornice, filling joints and cracks between the ashlar comprising the cornice (Fig. 3). After 1990, dissolved sulfur and calcium salt-laden rainwater leaking through the roof generated an ionic charge in the underlying cement mortar [14, 35]. These ionic solutions seeped into the dolostone beneath the cornice and flowed fairly freely inside the highly porous stone, working their way outward to the surface during the evaporation induced by the local climate (dry and very warm summers $>30^\circ\text{C}$ [20]). The restoration treatments used to reconstitute and conserve the outer ornaments prevented these solutions from exiting the stone, however (Fig. 15) [25].

Prevented by the presence of silicate consolidant inside the cracks, gypsum precipitated in the pores not penetrated by the conservation product. These pores were inter-connected by capillaries running across the treatment (Figs 14b and 15). Gypsum precipitation in the pores induced the growth of sub-spherical nodules up to $300\text{ }\mu\text{m}$ in diameter and internal stress as a result of crystallisation (Figs 8 and 14). These gypsum nodules were the saline crypto-efflorescences observed inside the dolostone, and whose formation could be explained in a similar way to the formation (controlled by substrate porosity) of evaporite nodules in sebkha zones (current geological environments characterised by climatic intense evaporation) [36-37].

During saline solution migration toward the stone surface, the salts precipitated, clustering under the surface treatments (restoration mortar or surface film) that they were unable to permeate (Figs 8, 13, 14a and 15). As a result, a layer of gypsum of varying thickness appeared between the surface treatments and the cracked-consolidated stone, especially where the bond between them was weak. The continuous crystallisation-induced stress of salts destabilised the restored ornament. These sub-efflorescent clusters underneath the coating film (acrylic resin) caused swelling, fissuring, flaking and detachment in both layers. When saline sub-efflorescence was located under the (epoxy and

346 acrylic resins) restoration mortar, scaling and surface detachment prevailed. Such types of decay
347 affected the restoration mortar, the gypsum layer and even part of the cracked dolostone, with the
348 total or partial loss of the restored ornament (Fig. 5).

349 After part of the treatments and the carved stone surface fell away, the rest of the carved stone
350 substrate (ornament) was weakened by the presence of salt efflorescence, which continued to induce
351 powdering and crumbling stone. The resulting detachment entailed the disappearance of valuable
352 decorative elements on the cornice restituted in 1990 [25].

353 In 2006 the apse was the object of further intervention, in which the cement bedding mortar was
354 replaced with lime mortar in the joints and cracks in the cornice, although the cement mortar
355 underneath the roof tiles was not removed. The cantilever was also enlarged slightly to protect the
356 cornice from the sun and rain, but no alternative system was devised to prevent rainwater from
357 leaking into the cement mortar and generating salts (gypsum). The cornice and its decorative
358 elements were again treated. The salts were eliminated with cellulose poultice; the most severely
359 damaged areas were consolidated with a mix of epoxy resin, marble powder and acetone; hydraulic
360 lime mortars physically similar to the stone were used to reconstitute the detached elements; and the
361 entire monument was consolidated by spraying its surface with an organo-siliceous product. Decay
362 may re-appear in the area, however, inasmuch as water will continue to leak across the cement in
363 the roof and evaporate outward to the surface of the cornice. Is a decay mechanism which acts from
364 the inside to outside. That notwithstanding, in the 2006 restoration preliminary studies were
365 conducted to determine the condition of the apse and how restoration might best be broached. A
366 number of restoration products and application techniques were tested, which to date (2015) have
367 not posed any conservation problems. On that occasion, the preliminary studies and restoration
368 works, conducted in 2005 and 2006, were well documented for use as guidance in future
369 interventions.

370

371 5. CONCLUSIONS

372 - The alarming decay on the ornamental part of the upper area of the Romanesque apse to San Juan
373 Bautista Church, restored in 1990, was the result of misguided intervention design and
374 implementation, in turn due to the want of a preliminary study that would have helped identify the
375 type of stone substrate, its conservation state and possible response to certain conservation
376 treatments.

377 - The variety of stone on the ornament-bearing apse modillions and cornice was identified as a very
378 porous, scantily durable dolostone decayed by rainwater leakage and surface runoff, along with the

379 concomitant salts. The forms of decay observed were internal cracking, flaking, scaling and surface
380 detachment.

381 - The use of cements and synthetic resins on a poorly conserved porous stone failed to meet the
382 general standards of effectiveness, suitability and durability required of conservation and restoration
383 treatments to ensure the physical stability of the restored area.

384 - Most of the ornaments restored in 1990 decayed and were lost in very short order due to the
385 appearance of an undesirable by-product (salts) of the restoration treatments applied.

386 - The use of portland cement mortars on the cornice and its joints led to the presence of ionic saline
387 solutions (gypsum) inside the dolostone.

388 - The silicate consolidant used to seal the cracks in the stone substrate on the cornice penetrated to a
389 suitable depth (1.5-2 cm) but was not 100 % effective, for some pores remained connected,
390 providing channels for the water and dissolved salts to migrate toward the surface. The salts
391 precipitating in these pores formed nodules that constituted saline crypto-efflorescences which,
392 while not the direct cause of decay, may have induced internal stress that weakened the surface
393 structure of the cracked stone.

394 - The epoxy and acrylic resins mortar used to reconstitute the lost ornamental elements stiffened and
395 hardened, obstructing the exit of the dissolved salts inside the stone. These salts precipitated
396 between the stone and the synthetic mortar, forming a layer of gypsum of varying thickness (saline
397 sub-efflorescence). The decay in these areas consisted primarily of scaling and possible detachment
398 either around the gypsum layer or the cracks in the dolostone, disfiguring the restored ornament.

399 - The acrylic resin water repellent applied rendered the surface glossy and changed the yellowish-
400 gold hue of the original dolostone to a greyish tone. Moreover, it blistered, fissured, flaked and
401 became detached, detracting from the appearance and condition of the cornice.

402 - The use of petrological techniques such as PM and SEM revealed the processes and agents
403 involved in the progressive decay of the Romanesque cornice restored in 1990 and the respective
404 mechanisms.

405

406 **Acknowledgements**

407 This study was funded under project of MICCIN (CGL2011-27902) and forms part of the
408 GEOMATERIALES-2CM (S2013/MIT-2914) research programme. The authors are members of
409 the Complutense University of Madrid's Research Group: "*Alteración y Conservación de los*
410 *Materiales Pétreos del Patrimonio*" (ref. 921349) and of the CEI-Moncloa (UCM-UPM) through
411 RedLabPat. Thanks are owed to the Archbishopric of Alcalá de Henares, Madrid, and all the

412 persons associated with the church in Talamanca for their assistance throughout this study.
413 Manuscript edited by Margaret Clark, professional translator and English language science editor.
414

415 REFERENCES

- 416 [1] Binda L, Saisi A, Tedeschi C. Compatibility of materials used for repair of masonry buildings: research
417 and applications. In: Kourkoulis SK editor. *Fracture and Failure of Natural Building Stone*. Springer
418 Netherlands; 2006, p. 167-182.
- 419 [2] Fort R, Varas MJ, Álvarez de Buergo M, Freire DM. Determination of anisotropy to enhance the
420 durability of natural stone. *Journal of Geophysics and Engineering* 2011; 8: S132-S144.
- 421 [3] Guardia-Olmedo JJ, Varas-Muriel MJ, Suárez-Medina FJ. Castle-Palace of La Calahorra, Granada:
422 Influence of climatic and architectural factors in the differential deterioration of stone masonries.
423 *Materiales de Construcción* 2013; 63 (312): 597-612.
- 424 [4] Ginell WS, Coffman R. Epoxy resin-consolidated Stone: Appearance change on aging (Architectural
425 restoration). *Studies in Conservation* 1998; 43 (4): 242-248.
- 426 [5] Banthia AK, Gupta AP. Role of acrylic resin in the conservation of deteriorated khondalite stones.
427 *Polymer Preprint (ACS)* 2000; 41(1): 277–278.
- 428 [6] Cnudde V, Cnudde JP, Dupuis C, Jacobs PJS. X-ray micro-CT used for the localization of water
429 repellents and consolidants inside natural building stones. *Materials Characterization* 2004; 53: 259–
430 271
- 431 [7] Vacchiano CD, Incarnato L, Scarfato P, Acierno D. Conservation of tuff-stone with polymeric resins.
432 *Construction and Building Materials* 2008; 22: 855–865
- 433 [8] López-Arce P, Gómez-Villalba L, Pinho L, Fernández-Valle ME, Alvarez de Buergo M. Fort R.
434 Influence of porosity and relative humidity on consolidation of dolostone with calcium hydroxide
435 nanoparticles: Effectiveness assessment with non destructive techniques. *Materials Characterization*
436 2010; 61: 168–184
- 437 [9] Washington 1987 Charter. Charter for the conservation of historic towns and urban areas. ICOMOS
438 General Assembly in Washington, DC, 1987. <http://www.icomos.org/en/charters-and-texts>
- 439 [10] ICOMOS 1996. Principles for the recording of monuments, groups of buildings and sites. 11th ICOMOS
440 General Assembly in Sofia, 1996. <http://www.icomos.org/en/charters-and-texts>
- 441 [11] ICOMOS 2003 Charter. Principles for the analysis, conservation and structural restoration of
442 architectural heritage. 14th ICOMOS General Assembly in Victoria Falls, Zimbabwe, 2003.
443 <http://www.icomos.org/en/charters-and-texts>

- 444 [12] Varas MJ, Álvarez de Buergo M, Pérez-Monserrat E, Fort R. Decay of the restoration render mortar of
445 the church of San Manuel and San Benito, Madrid, Spain: Results from optical and electron
446 microscopy. *Materials Characterization* 2008; 59 (11): 1531-1540.
- 447 [13] Domingo C, Alvarez de Buergo M, Sánchez-Cortés S, Fort R, García-Ramos JV, Gómez-Heras M..
448 Possibilities of monitoring the polymerization process of silicon-based water repellents and consolidants
449 in stones through infrared and Raman spectroscopy. *Process in Organic Coatings* 2008; 63: 5-12.
- 450 [14] Pecchioni E, Gomez-Ubierna M, Cagnini A, Galeotti M, Fratini F, Porcinai S. Ancient and new repair
451 mortars for conservation: application to the case of San Leonardo Pulpit (Florence, Italy). *International*
452 *Journal of Architectural Heritage* 2014; 8 (4): 556-580.
- 453 [15] Nóvoa PJRO, Ribeiro MCS, Ferreira AJM, Marques AT. Mechanical characterization of lightweight
454 polymer mortar modified with cork granulates. *Composites Science and Technology* 2004; 64: 2197-
455 2205.
- 456 [16] Álvarez de Buergo Ballester M, Fort-González R. Basic methodology for the assessment and selection
457 of waterrepellent treatments applied on carbonatic materials. *Prog Org Coat* 2001; 43: 258– 266
- 458 [17] Varas MJ, Álvarez de Buergo M, Fort R. The influence of past protective treatments on deterioration of
459 historic stone façades: A case study. *Studies in Conservation* 2007; 52: 110-125
- 460 [18] Álvarez de Buergo M, Fort R, Gómez-Heras M. Contributions of SEM to the assessment of the
461 effectiveness of stone conservation treatments. *Scannig* 2004; 26 (1): 41-47.
- 462 [19] Van Hees RPJ, Binda L, Papayianni I, Toumbakari E. Characterisation and damage analysis of old
463 mortars. *Materials and Structures* 2004; 37 (273): 644-648.
- 464 [20] Varas-Muriel MJ, Fort R, Martínez-Garrido MI, Zornoza-Indart A, López-Arce P. Fluctuations of the
465 indoor environment in Spanish rural churches and their effects on heritage conservation: hygro-thermal
466 and CO₂ conditions monitoring. *Building and Environment* 2014; 82: 97-109.
- 467 [21] Valluzi RM, Binda L, Modena C. Experimental and analytical studies for the choice of repair techniques
468 applied to historic buildings. *Materials and Structures* 2002; 35 (249): 285-292.
- 469 [22] Ibáñez-Gómez JA, Yusta I, García-Garmilla F, Cano M, Rodríguez-Maribona I, Beraza K, Garín S.
470 Chemical and mineralogical study of restoration mortars applied to the Eocene sandstones of Gipuzkoa
471 used for building construction. *Geogaceta* 2001; 30: 223-226.
- 472 [23] López-Arce P, Zornoza-Indart A, Gómez-Villaba LS, Fort R. Short- and Longer-Term Consolidation
473 Effects of Portlandite Ca(OH)₂ Nanoparticles in Carbonate Stones. *Journal of Material Civil*
474 *Engineering* 2013; 25: 1655-1665.
- 475 [24] Fort R, Álvarez de Buergo M, Pérez-Monserrat E, Gómez-Heras M, Varas-Muriel MJ, Freire DM.
476 Evolution in the use of natural building stone in Madrid, Spain, *Quarterly Journal of Engineering*
477 *Geology and Hydrogeology* 2013; 46: 421-429.

- 478 [25] Vázquez-Calvo C, Varas MJ, Pérez-Monserrat E, Álvarez de Buergo M, Fort R. The causes of the
479 accelerated stone decay by means of optical Microscopy and SEM-EDS. In: Abstract book, 11th
480 Euroseminar on Microscopy Applied to Building Materials. Porto, Portugal, 2007: 109-110.
- 481 [26] UNE-EN 12407. Métodos de ensayo para piedra natural. Estudio Petrográfico. Asociación Española de
482 Normalización y Certificación (AENOR), Madrid, 2007.
- 483 [27] Lindholm RC, Finkelman RB. Calcite staining: semiquantitative determination of ferrous iron. *Journal*
484 *of Sedimentary Petrology* 1972; 42: 239- 242.
- 485 [28] Derrick MR, Strulik D, Landry JM. *Infrared Spectroscopy in Conservation Science. Scientific Tools for*
486 *Conservation*. Getty Conservation Institute, USA; 1999, 235p.
- 487 [29] UNE-EN 1936. Métodos de ensayo para piedra natural: Determinación de la densidad real y aparente y
488 de la porosidad abierta y total. Asociación Española de Normalización y Certificación (AENOR),
489 Madrid, 2007.
- 490 [30] UNE-EN 14579. Métodos de ensayo de piedra natural. Determinación de la velocidad de propagación
491 del sonido. Asociación Española de Normalización y Certificación (AENOR), Madrid, 2005.
- 492 [31] Dunham RJ, Classification of carbonate rocks according to depositional texture. In: Ham WE editor.
493 *Classification of carbonate rocks: American Association of Petroleum Geologists Memoir*; 1962, p.
494 108-121.
- 495 [32] Fort R, Fernández-Revuelta B, Varas MJ, Álvarez de Buergo M, Taborda M. Influence of anisotropy on
496 the durability of Madrid-region Cretaceous dolostone exposed to salt crystallization processes.
497 *Materiales de Construcción* 2008; 58 (289-290): 161-178.
- 498 [33] Young ME, Cordiner P, Murray M. Chemical consolidants and water repellents for sandstones in
499 Scotland. *Edinburgh, Scotland Historic Scotland Research Report*; 2003, 265 p.
- 500 [34] López-Arce P, Fort R, Gómez-Heras M, Pérez-Monserrat E, Varas-Muriel MJ. Preservation strategies
501 for avoidance of salt crystallisation in El Paular Monastery cloister, Madrid, Spain. *Environmental Earth*
502 *Sciences* 2011; 63 (7-8): 1487-1509.
- 503 [35] Varas MJ, Álvarez de Buergo M, Fort R. Natural cement as the precursor of Portland cement:
504 methodology for its identification. *Cement and Concrete Research* 2005; 35(11): 2055-2065.
- 505 [36] Machel HG, Burton EA. Burial - diagenetic sabkha - like gypsum and anhydrite nodules. *Sedimentary*
506 *Geology* 1991; 61: 394-405.
- 507 [37] Zamannejad A, Jahani D, Lotfpour M, Movahed B. Mixed evaporite/carbonate characteristics of the
508 Triassic Kangan Formation, offshore area, Persian Gulf. *Revista mexicana de Ciencias Geológicas*
509 2013; 30 (3): 540-551.

512 FIGURE CAPTIONS

513 Fig. 1. Twelfth-thirteenth century Romanesque apse on church at Talamanca de Jarama, Madrid,
514 Spain, whose upper stone ashlar are yellow and lower rough ashlar beige dolostone; occasional
515 white limestone cladding

516 Fig. 2. Richly carved cornice and modillions on the upper part of the church, restored in 1990:
517 cement mortar filling in inter-ashlar joints and laid directly on the cornice underneath the Spanish
518 tile roof

519 Fig. 3. Decaying cornice and modillions in 2004, showing substantial amounts of cement on the
520 cornice and the near total loss of ornaments on modillions and cornice

521 Fig. 4. Samples of dolostone on around the cornice: a) cross-section of yellow dolostone core: b)
522 decayed fragment from cornice surface, showing the obvious contrast between the glossy grey
523 treatments and the yellowish dolostone

524 Fig. 5. Grey treatment scaling and flaking on cornice and modillions, baring the yellow stone
525 substrate and inducing the loss of the original restored ornament

526 Fig. 6. Cross-section of scale removed from cornice, showing three zones: upper grey layer with
527 white particles and varying depth (restoration mortar), middle layer where the stone substrate
528 exhibits cracks parallel to the surface and a few white spots, and lower layer where the yellow
529 substrate is compact

530 Fig. 7. PM images of yellow dolostone on the upper part of the apse: a) no decay but substantial
531 original porosity (left: parallel nicols; right: crossed nicols); and b) cracks and nodules indicative of
532 decay (parallel nicols)

533 Table 1. Petrophysical properties of decayed (outer 5 cm) and undecayed (at depths of 5-10 cm)
534 dolostone

535 Fig. 8. Scaling on cornice: a) PM image with parallel nicols; b) μ XRD diffractogram showing the
536 mineralogy of the two components of the restoration mortar; c) SEM-SE image of a thin section: A
537 - restoration mortar, B – gypsum layer, C - cracked stone substrate with gypsum nodules

538 Fig. 9. SEM-SE image of a fragment of restoration mortar and EDS point chemical composition: A
539 - binder; B – aggregate

540 Fig. 10. FTIR spectrum of restoration mortar

541 Fig. 11. Fragment of restoration mortar surface, showing: A - surface acrylic, B - binder and C -
542 aggregate (both in the underlying restoration mortar), under: a) PM (parallel nicols) and b) SEM-
543 SE. EDS point chemical composition of synthetic resins (A - acrylic and B - epoxy+acrylic)
544 forming part of the two treatments (with Ca as the sole chemical element in the C - aggregate)

545 Fig. 12. FTIR spectrum of resin film

546 Fig. 13. SEM-SE image and EDS point chemical composition of a scaling fragment, showing: A -
547 surface treatment, B - restoration mortar, C - gypsum layer and D - cracked stone substrate
548 Fig. 14. PM (parallel nicols) images of: a) gypsum nodules inside the cracked dolostone; and b)
549 capillary connections.
550 Fig. 15. Mechanism governing post-1990 intervention decay in cornice and modillions: 1 - acrylic
551 surface treatment; 2 - synthetic restoration mortar; 3 - gypsum layer; 4 - cracked dolostone with
552 gypsum nodules; A - rainwater leakage; B - surface runoff.

553

554 **Highlights**

- 555 Long-term effectiveness, suitability and durability of conservation treatments
- 556 Need for preliminary studies to ensure successful restoration
- 557 Use of petrological techniques to determine treatment mechanisms
- 558 Unsuitable use of cements and synthetic resins on decayed dolostone
- 559 Salt-induced loss of restored ornaments

560

Fig. 1



Fig. 2





Fig. 3




Fig. 4



Fig. 5



Fig. 6




Fig. 7a




Fig. 7b

Table 1

	Dolostone	
	outer area	inner area
Real density (kg m^{-3})	2 821	2 824
Bulk density (kg m^{-3})	2 077	2 237
Open porosity (%)	26.36	24.31
Water absorption (%)	12.69	11.38
Vp (m s^{-1})	1 843	2 873

Vp - ultrasonic P-waves pulse velocity




Fig. 8




Fig. 9




Fig. 10




Fig. 11





Fig. 12

Fig. 13






Fig. 14




Fig. 15